

Certificate of Accreditation: Supplement

JASTI Technical Center

669 Yanagisawa Numazu, Shizuoka 410-0308 Contact Name: Yoshihiro Ozawa Phone: 055-966-8620

Accreditation is granted to the facility to perform the following testing:

Mechanical F Dummy 95th, 50th, 5th Foot Ass'y St-9 Stand Autograph Foot Compression Test Step Stand Autograph Foot Compression Test Test Dummy/ SAE J2856 User's Manual for the 50th Percentile Male Hybrid III Dummy/ SAE J2862 User's Manual for the 50th Percentile Male Hybrid III Dummy/ SAE J2862 User's Manual for 10 % to 70 %	FIELD OF TEST	ITEMS, MATERIALS OR PRODUCTS TESTED	SPECIFIC TESTS OR PROPERTIES MEASURED	SPECIFICATION, STANDARD METHOD OR TECHNIQUE USED	RANGE (WHERE APPROPRIATE) AND DETECTION LIMIT
the Small Adult Female H III Test Dummy Measuring instruments: Displacement Gauge Load Cell	Mechanical ^F	Dummy 95th, 50th, 5th	Autograph	On the basis of: SAE J2860 User's Manual for the Hybrid III Large Male Test Dummy/ SAE J2856 User's Manual for the 50th Percentile Male Hybrid III Dummy/ SAE J2862 User's Manual for the Small Adult Female H III Test Dummy Measuring instruments: Displacement Gauge	Force: 0 N to 667 N Deflection: 0 mm to 8.9 mm Temperature: 20.6 °C to 22.2 °C Humidity:

1. The presence of a superscript F means that the laboratory performs testing of the indicated parameter at its fixed location. Example: Outside Micrometer F would mean that the laboratory performs this testing at its fixed location.

